

FULL FLOW BALL VALVES: IDEAL

098S Ideal ball valve with o-ring, full flow for manifolds

LOSS DIAGRAM (With water)

	1/2"	3/4"	3/4"X1"	1"	1"1/4	
KV	15,65	26,26	26,26	41,44	63,69	
psi bar 14,5— 1—	m H ₂ O KPa 10 100 100 1					Ŧ



