



SWING CHECK VALVE

130 Swing check valve

LOSS DIAGRAM (With water)

130M

	3/8"	1/2"	3/4"	1"	1"1/4"	1"1/2"	2"	2"1/2"	3"	4"
KV	-	3,6	9,5	23	35	56	86	222	360	540

130G

	3/8"	1/2"	3/4"	1"	1"1/4"	1"1/2"	2"
KV	-	3,6	9,5	23	35	56	86

