



STRAINERS

192 Y strainer

LOSS DIAGRAM (With water)

	1/4"	3/8"	1/2"	3/4"	1"	1 1/4"	1 1/2"	2"
KV	1,7	2,4	3,5	6,5	8	10	11,5	19,6

