291XB Ideal ball valve, full flow, with flat lever handle in stainless steel

PRESSURE-TEMPERATURE DIAGRAM

7

The values shown by the dropping lines state the maximum limit of employment of the valves. The shown values are approximate.



