



# SWING CHECK VALVE

## 130 Swing check valve

### PRESSURE-TEMPERATURE DIAGRAM

The values shown by the dropping lines state the maximum limit of employment of the valves.  
The shown values are approximate.

