



FULL FLOW BALL VALVES: IDEAL

290XB Ideal ball valve, full flow, with flat lever handle in stainless steel

LOSS DIAGRAM (With water)

| | 1/4" | 3/8" | 1/2" | 3/4" | 1" | 1 1/4" | 1 1/2" | 2" |
|----|------|------|-------|-------|-------|--------|--------|-----|
| KV | 3,45 | 5,00 | 15,65 | 26,26 | 41,44 | 63,69 | 101 | 169 |

