



# FULL FLOW BALL VALVES: IDEAL

## 291XB Ideal ball valve, full flow, with flat lever handle in stainless steel

### LOSS DIAGRAM (With water)

	1/4"	3/8"	1/2"	3/4"	1"	1 1/4"	1 1/2"	2"
KV	3,45	5,00	15,65	26,26	41,44	63,69	101	169

