




MANUAL VALVES AND LOCKSHIELDS

296S Straight lockshield

LOSS DIAGRAM (With water) size 3/8"

	3/8"	1/2"	3/4"
KV	1turn:0,4;2turn:0,9;3turn:1,1;MA X:1,26	1turn:0,6;2turn:1,2;3turn:1,6;MA X:1,72	1turn:0,6;2turn:0,9;3turn:1,5;MA X:2,15






MANUAL VALVES AND LOCKSHIELDS

LOSS DIAGRAM (With water) size 1/2"

	3/8"	1/2"	3/4"
KV	1turn:0,4;2turn:0,9;3turn:1,1;MA X:1,26	1turn:0,6;2turn:1,2;3turn:1,6;MA X:1,72	1turn:0,6;2turn:0,9;3turn:1,5;MA X:2,15





MANUAL VALVES AND LOCKSHIELDS

LOSS DIAGRAM (With water) size 3/4"

	3/8"	1/2"	3/4"
KV	1turn:0,4;2turn:0,9;3turn:1,1;MA X:1,26	1turn:0,6;2turn:1,2;3turn:1,6;MA X:1,72	1turn:0,6;2turn:0,9;3turn:1,5;MA X:2,15

