




ACCESSORIES FOR MANIFOLDS

485 Thermometer and pressure gauge, back connection

MATERIALS



POS.	DESCRIPTION	N.	MATERIAL
1	Body	1	ABS
2	See-through cap	1	Altuglas®
3	Quadrant	1	Aluminium
4	Indicator	1	Nylon
5	Indicator	1	Nylon