




## 610 Соединение прямое ВР

### ГАБАРИТНЫЕ РАЗМЕРЫ



	12x3/8"	12x1/2"	14x1/2"	15x1/2"	16x1/2"	18x1/2"	18x3/4"	20x1/2"	22x3/4"	25x3/4"	28x1"
A	51,6	55	55	55	55	59	59,6	62	62	64	70
B	23	23	25	26	27	31,5	31,5	34	36	40	43,7